

STATE OF IDAHO
DEPARTMENT OF FISH AND GAME
FEDERAL AID IN FISH AND WILDLIFE RESTORATION

Supplemental
to
Slate Creek Stream Improvement
covering report
F 14-D-1

The following figures are intended to supplement those in the original report covering stream improvement structures to Slate Creek and submitted under date of January 3, 1954, prepared by Paul Jeppson.

Paul Jeppson, Project Leader



Figure 13. Slate Creek. May 17, 1955. Same as Figure 1 after peak of high water.



Figure 14. Slate Creek. May 17, 1955. Same as Figure 4 after peak of high water. Structure 10 from downstream view.



Figure 15. Slate Creek. July 30, 1954. Structure 11 before runoff.




Figure 16. Slate Creek. May 17, 1955. Structure 11 during runoff.
(Same as Figure 15)



Figure 17. Slate Creek. May 17, 1955. Structure 12 after peak of high water. Same as Figure 6.



Figure 18. Slate Creek. May 17, 1955. Structure 13 during runoff. Compare with Figure 7.



Figure 19. Slate Creek. May 17, 1955. Structure 14 during spring runoff.



Figure 20. Slate Creek. May 17, 1955. Structure 17 during spring runoff.



Figure 21. Slate Creek. May 17, 1955. Upstream view of structure 18 during spring runoff. Compare with Figure 10.



Figure 22. Slate Creek. May 17, 1955. Structure 20 during spring runoff.



Figure 23. Slate Creek. May 17, 1955. Upper part of structure 20 during runoff.



Figure 24. Slate Creek. May 17, 1955. Structure 22 during runoff. Compare with Figure 12.